

FORKLIFT OPERATOR

Next class not until September!!!

WHEN:

July 6th, 2010

WHERE:

SBE Training Center
2985 Innsbruck Drive

TIME:

8:00am-12:00pm—Classroom
1:00pm—Hands-On Evaluation

COST:

\$100.00 SBE Members
\$125.00 Assoc. & Prof. Members
\$150.00 Non-members

THIS TRAINING IS **REGULAR,**
COUNTER-BALANCE FORKLIFT.
ROUGH TERRAIN TRAINING ONLY
AVAILABLE UPON REQUEST FOR AN
ADDITIONAL CHARGE.

**ALL EMPLOYEES WHO OPERATE FORKLIFTS MUST BE
TRAINED & CERTIFIED!!!**

This class will present the “5 W’s (Who, What, When, Why, and Where) of Forklift Operation and Certification.” This includes:

1. Instruction on forklift fatalities and injuries.
2. Forklift stability and center of gravity.
3. Operating rules.
4. Load handling.
5. Training and certification regulations.
6. Pre-shift inspections.
7. Hands on instruction.
8. On-site evaluations.



**Cal-OSHA now recommends
recertification every 3 years!!**

**ELECTRICIAN
CEU's - 6 HRS
JOURNEYPERSON**

To register simply fill in this form
and **FAX BACK TO 222-1918** or
Complete this form and mail
along with your check to:
SBE Training Center
2985 Innsbruck Drive
Redding, CA 96003
If you have any questions please
call (530) 222-1917

Name _____

Company _____

Address _____

Phone _____

Method of Payment
 Bill my SBE Account MasterCard
 Check Enclosed Visa

Credit Card # _____ Exp. date _____

Signature _____

Attendees:



REGISTRATION / CANCELLATION POLICIES

Non-Members MUST pay in advance to reserve their space(s).
All registration is on a 1st come 1st serve basis until the seminar is full.
Late cancellation fees will be billed at 50% of the seminar price. No shows will be billed full seminar price.
To avoid being billed you must cancel no later than 5 business days prior to training by 5:00PM.
LATE CANCELLATIONS = NO REFUNDS ~ NO CREDITS ~ NO ROLLING FORWARD ~ NO EXCEPTIONS.
The SBE Training Center reserves the right to cancel class due to low enrollment.

To be removed from our contact list, please call 222-1917 or e-mail removeme@shastabe.com